



Glensanda Harbour

NOTICE TO MARINERS 11/23

1st November 2023

With immediate effect the certified depth alongside Glensanda Armour Stone Loading Jetty is reduced to 4.2m CD. Vessels at the jetty must maintain a minimum underkeel clearance of 0.6m at all times. Draft should be monitored at all stages of loading, and particularly if on deep draft over periods of low tide.

The restriction is evident adjacent to the lower deck of the berth around its mid point.

This restriction will remain in effect until notified otherwise. Measures are being taken to restore the full cleared depth of 5.0 CD.

I.F.Henry
Harbour Master